




Use any electronic gauging device for part measurement...



...and **AUTOCOMP** will automatically calculate and compensate tool offsets (in the control).

Real-Time Data



Historical Part Data

■ Part is Good    
 ■ Compensation Required    
 ■ Out of Tolerance

- Eliminates human error
- Statistically controls tool offsets to maintain acceptable tolerances
- Interfaces directly with the CNC control for process optimization
- Notifies the operator when a tool change is needed; with option to set a flag for redundant tooling
- Essential for closed loop and lean manufacturing

*No manual data entry or operator intervention needed!*

